General Information and Fire/Life Safety History

Inspection Date: 7/1/25 1. Primary Use: INSTRUCTIONAL 2. Fire Sprinkler System? No 2a. Sprinkler alarm? No 3. Fire Hydrant System? Yes 3a. Hydrant Ownership: Public owned 4. Building Ownership: Owned 5. Leased To Others?: No 6. Square footage: 55289 8a. Fire drill manuals distributed? Yes 8d. Average evacuation time: 1 minutes 16 seconds 8e. Arson/Fire Prevention? Yes 8f. Prevention/Evacuation Training? Yes 9. Fire Dept. notified via alarm? Yes 10. Any Fires? No 10a. Number of fires: Not Applicable 10b. Number of injuries: Not Applicable 10c. Cost of Damage: Not Applicable **Inspector Notified of previous fire report?**

FIRE & EMERGENCY DRILLS

	Date	Type
	Sep 10, 2024	Evacuation
:	Sep 12, 2024	Evacuation
:	Sep 20, 2024	Evacuation
	Sep 27, 2024	Evacuation

Yes

	Date	Туре
5	Oct 3, 2024	Evacuation
6	Oct 7, 2024	Evacuation
7	Oct 15, 2024	Lockdown
8	Oct 17, 2024	Lockdown
9	May 28, 2025	Evacuation
10	May 29, 2025	Evacuation
11	Jun 2, 2025	Lockdown
12	Jun 3, 2025	Lockdown

Initial Inspector

Christopher Jones

Phone #: (Phone Number) (518) 746-2189

<u>Certification #: (Certification Number)</u> 1020-0233

Email: cjones@washingtoncountyny.gov

Building Administrator

Joseph Manney

Phone #: (Phone Number) (518) 681-4571

Building Overview

ID:

641301060004

District Location:

HUDSON FALLS CSD

Building Type:

INSTRUCTIONAL

Name & Address:

HUDSON FALLS INTERMEDIATE SCHOOL 135 MAPLE ST

HUDSON FALLS, NY 12839

Inspection History

Date Created:

Jul 8, 2025

Created By:

joseph.manney

Date Modified:

Jul 8, 2025

Modified By:

daniel.ward4

Date Certified:

Jul 8, 2025

Certified By:

daniel.ward4

Certificate History

Certificate Type

Date Certified

Certified By

Certificate of Occupancy

Jul 8, 2025

daniel.ward4

Non-conformances

No non-conformances reported.

NYSED Home Facilities Planning Home Home Terms of Use Accessibility Privacy Policy